

# 点火マップ(H18.7.2時点)柿本HYPER2000FullmegaN1Single(触媒なし)初期値との比較

## 回転数

400rpm 800rpm 1200rpm 1600rpm 2000rpm 2400rpm 2800rpm 3200rpm 3600rpm 4000rpm 4400rpm 4800rpm 5200rpm 5600rpm 6000rpm 6400rpm 6800rpm 7200rpm 7600rpm 8000rpm

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20

1	16	16	16	17	27	44	50	54	54	51	51	51	51	51	51	51	51	51	51
2	16	16	16	17	27	44	50	54	54	51	51	51	51	51	51	51	51	51	51
3	16	16	16	35	41	44	50	54	54	51	51	51	51	51	51	51	51	51	51
4	20	21	27	35	41	44	50	54	54	51	51	51	51	51	51	51	51	51	51
5	19	20	25	30	36	39	44	49	49	46	46	46	46	46	46	46	46	46	46
6	17	20	23	27	34	38	41	42	39	36	36	36	36	39	41	42	43	42	41
7	15	18	20	24	31	36	37	37	38	33	33	34	33	36	38	40	40	40	39
8	9	16	20	22	28	34	35	36	37	32	32	33	32	34	38	39	39	39	38
9	9	14	19	21	27	31	32	34	35	32	32	33	30	32	35	37	38	38	37
10	9	13	16	19	24	28	30	30	31	30	30	30	28	29	32	34	35	36	36
11	9	14	17	18	22	26	28	29	24	27	25	27	26	27	30	31	32	33	33
12	9	13	17	18	21	24	25	25	27	24	25	25	25	25	27	28	29	31	31
13	9	13	17	18	19	19	19	22	24	21	22	23	24	23	23	25	26	28	28
14	9	13	16	17	15	15	14	18	20	18	18	18	20	19	21	21	21	22	22
15	9	13	16	15	14	14	11	16	17	15	16	16	18	17	18	19	21	21	21
16	9	13	16	12	11	12	11	13	15	15	14	15	15	17	18	18	20	20	20
17	9	13	16	11	10	11	11	11	16	13	13	14	14	16	17	18	20	20	20
18	9	13	16	10	9	10	10	11	15	12	12	14	14	16	16	17	19	19	19
19	9	13	16	8	7	7	10	11	14	12	12	14	14	16	17	17	19	19	19
20	9	13	16	7	6	6	10	11	13	12	12	14	14	16	17	17	19	19	19

初期からの変化量

- 1度進角
- 2度進角
- 3度進角
- 4度進角
- 1度遅角
- 2度遅角
- 3度遅角
- 初期値又は4度以上の遅角

コメント  
・  
履歴

フィーリング: