

# 点火マップ(H18.7.12時点)柿本HYPER2000FullmegaN1Single(触媒なし)初期値との比較

## 回転数

400rpm 800rpm 1200rpm 1600rpm 2000rpm 2400rpm 2800rpm 3200rpm 3600rpm 4000rpm 4400rpm 4800rpm 5200rpm 5600rpm 6000rpm 6400rpm 6800rpm 7200rpm 7600rpm 8000rpm

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20
16	16	16	17	27	44	50	54	54	51	51	51	51	51	51	51	51	51	51	51
16	16	16	17	27	44	50	54	54	51	51	51	51	51	51	51	51	51	51	51
16	16	16	35	41	44	50	54	54	51	51	51	51	51	51	51	51	51	51	51
20	21	27	35	41	44	50	54	54	51	51	51	51	51	51	51	51	51	51	51
19	20	25	30	36	39	44	49	49	46	46	46	46	46	46	46	46	46	46	46
17	20	23	26	33	38	41	42	39	36	32	32	32	35	37	38	39	39	39	39
15	18	20	23	30	36	37	37	38	33	29	30	29	32	34	36	36	37	37	37
9	16	20	21	27	34	35	35	37	32	28	29	28	30	34	35	35	36	36	36
9	14	19	21	27	31	32	34	35	32	28	29	26	28	31	33	34	35	35	35
9	13	16	19	24	28	29	30	30	28	28	28	26	27	30	32	33	33	34	34
9	14	17	18	22	26	28	29	24	27	25	25	24	25	28	29	30	31	31	31
9	13	17	18	21	24	24	25	27	24	25	23	23	23	25	26	27	29	29	29
9	13	17	18	19	18	18	22	24	21	22	21	22	21	21	23	24	26	26	26
9	13	16	17	15	15	14	18	20	18	18	18	20	19	19	20	20	21	21	21
9	13	16	15	14	14	11	16	17	15	16	16	16	15	16	18	20	20	20	20
9	13	16	12	11	12	11	13	15	15	14	15	15	15	16	17	19	19	19	19
9	13	16	11	10	11	11	11	16	13	13	14	14	14	15	17	19	19	19	19
9	13	16	10	9	10	10	11	15	12	12	14	14	14	16	17	18	18	18	18
9	13	16	8	7	7	10	11	14	12	12	14	14	14	17	17	18	18	18	18
9	13	16	7	6	6	10	11	13	12	12	14	14	14	17	17	18	18	18	18

初期からの変化量

1度進角
2度進角
3度進角
4度進角
1度遅角
2度遅角
3度遅角
4度遅角

初期値は色無し

コメント  
・  
履歴

フィーリング: